

1/12
Willner et al.
YOR920010043US1




FIG. 1

2/12
YOR920010043US1




FIG. 2

3/12
YOR920010043US1




FIG. 3

4/12
YOR920010043US1




FIG. 4

5/12
YOR920010043US1




FIG. 5

6/12
YOR920010043US1




FIG. 6

7/12
YOR920010043US1




FIG. 7

8/12
YOR920010043US1




FIG. 8

9/12
YOR920010043US1

900 →

PROGRAM IDENTIFIER <u>902</u>	DESCRIPTION <u>904</u>	FILE <u>906</u>
ECP-1001	EMISSION CONTROL DRIVER V1.4.1	ECD141.EXE
ECP-1002	EMISSION CONTROL DRIVER V1.5	ECD150.EXE
ECP-1003	TRANSMISSION CONTROL PROGRAM	WWW.FORD.ORG/ TCP1001
ECP-1004	FUEL INJECTION SOFTWARE	FIS1001.EXE

FIG. 9

10/12
YOR920010043US1

1000 →

RULE IDENTIFIER	CONDITION	ACTION
<u>1002</u>	<u>1004</u>	<u>1006</u>
DR-1001	CO-1003 < ECD1.5	OFFER TO INSTALL ECP-1002
DR-1002	DI-1004 = 93	SELECT ECP-1004
DR-1003	DI-1002 > 200° C	ADJUST ECP-1003

FIG. 10

11/12
YOR920010043US1

1100 →

TRANSACTION IDENTIFIER: T10001		
	<u>1102</u>	
CONSUMING DEVICE IDENTIFIER: CD1001	<u>1104</u>	
PAYMENT IDENTIFIER: 1111-2222-3333-4444	<u>1106</u>	
DATE AND TIME: 07-04-03 AT 11:45 AM	<u>1108</u>	
TRANSACTION TOTAL: \$23.50	<u>1110</u>	
TRANSACTION STATUS: COMPLETE		
<u>1112</u>		
ITEM IDENTIFIER	DESCRIPTION	COST
<u>1114</u>	<u>1116</u>	<u>1118</u>
F-1001	89 (10 GALLONS)	\$21.00
ECP-1002	ECD150.EXE INSTALLED	\$2.50

FIG. 11

12/12
YOR920010043US1

1200 →

PARAMETER IDENTIFIER	DESCRIPTION	CURRENT VALUE
<u>1202</u>	<u>1204</u>	<u>1206</u>
CO-1001	VEHICLE IDENTIFIER	FORD-1001
CO-1002	ENGINE TEMPERATURE	155° C
CO-1003	EMISSIONS CONTROL DRIVER VERSION	ECD1.4.1
CO-1004	PREFERRED OCTANE RATING	89

FIG. 12